

SERVICE BULLETIN



No. : 0IVL20050035

Date : 2005-11-08

Model	Factory	Factory Model	Suffix	Model No.	Factory	Factory Model	Suffix	Model No.
	EKHQ	32LX3DC-UA	ALUSLV	32LX3DC-UA	ENMX	32LX3DC-UA	ALUSLL	32LX3DC
	ENMX	32LX3DC-UA	ALUSLV	32LX3DC	EKHQ	32LX3DCS-UA	ALUSLV	32LX3DCS-UA
	ENMX	32LX3DCS-UA	ALUSLL	32LX3DCS	ENMX	32LX3DCS-UA	ALUSLV	32LX3DCS
Buyer	Buyer Name	Buyer Code	Buyer Name	Buyer Code	Buyer Name	Buyer Code		
	LGEUS	US000001	LGEAI	US000002				
EFFECTIVE DATE	2005-11-08		EFFECTIVE FROM(SERIAL NO.)			All of range.		
Subject	32LX3DC/S S-Video image distortion on side jack input.							
No.	Loc No.	Before Change		After Change		Note	K-Code	Remark
		Part No	DESC./SPEC.	Part No	DESC./SPEC.			
Reason Of Change								
<p>Problem : Distortion when using S-Video side jack.</p> <p>Model : 32LX3DC-UA, 32LX3DCS-UA</p> <p>Cause : Missing S-Video Y/C signal-ground.</p> <p>Refer to attached file.</p>								
32LX3DC_Video_Distortion.pdf								

** FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

NOTE(**) : INTERCHANGEABILITY CODE				KEY-WORD CODE	
	Parts	Set		1. To improve performance 2. To improve productivity 3. To improve reliability 4. Change of material or dimension 5. Addition 6. Deletion 7. Correction	
A	Original	Early	Original or new parts may be used in early or late production sets.		
	New	Late	Use original parts until exhausted, then stock new parts.		
B	Original	Early	Original parts may be used in early production sets only. New parts may be used in early or late production sets.		
	New	Late	Use original parts where possible, then stock new parts.		
C	Original	Early	New parts only may be used in early or late production sets.		
	New	Late	Stock new parts.		
D	Original	Early	Original parts only may be used in early production sets. New parts may be used in late production sets only.		
	New	Late	Stock original and new parts.		

CHIEF ENGINEER , *approved*
Factory.